



**Keystone RV  
Company™**

**RECREATIONAL VEHICLE  
SAFETY RECALL NOTICE**

Safety Recall: 16V-908  
Transport Canada: 2016-626  
Safety Advisory: 16-274  
January 13, 2017

**Recall Population:**

<b>Models</b>		<b>Serial Numbers</b>
2017 Carbon	Model 337	HR805330
2016 Fuzion	Model 414	GF810953
2017 Fuzion	Models 325, 345, 369, 371, 384, 385, 413, 4141, 414, 417, 4201, 420, 4221, 4231, 423	HF810341 – HF810698
2017 Raptor	Models 362, 424TS, 428SP	HR800295 – HR800492
2016 Voltage	Models 3005, 3200, 3305, 3605, 3805, 3818, 3895, 3914, 3970, 3990, 4000, 4105, 4150	GZ990613 – GZ991354
2017 Voltage	Models 3005, 3305, 3605, 3655, 3805, 3815, 3890, 3895, 3970, 3975, 3990, 3995, 4005, 4100, 4105, 4155	HZ990000 – HZ990964

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in the vehicles listed above. As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

***Reason for  
this recall***

It has been decided the vehicles in this recall population may have been manufactured with a MORryde ramp door hinge which could separate from the door frame due to an incorrect weld on the hinge pin. If the hinge pin separates the ramp door may pull loose from the vehicle while an individual is utilizing the door, leading to an increased risk of personal injury.

***What we  
will do***

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. The remedy is to replace the ramp door hinge. The service and parts required for this corrective action will be provided at no charge to you.

***What we  
need you to  
do***

As soon as possible, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately 1 ½ hours. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

***If you have  
questions***

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. Please contact Keystone Customer service if your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you. You may be eligible to receive reimbursement if you paid to have the defect resolved prior to receiving this correspondence. Keystone Customer Service is available toll-free at 1-866-425-4369.

If after contacting Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>.)



**PO Box 2000 – Goshen, IN 46527-2000  
Phone: (574) 535-2100 – Fax: (574) 535-2199  
[www.keystonerv.com](http://www.keystonerv.com)**