



RECREATIONAL VEHICLE SAFETY RECALL NOTICE

Original Notification Date December 8, 2010
NHTSA # 10V-606
Transport Canada # 2010-429
Keystone # 10-152

Recall Population

2011 Sprinter Travel Trailers and Fifth Wheels Production Dates: 6/10/2010 – 9/2/2010
VIN Range: 4YDT27621**B1531081** - 4YDT29B29**B1532142**

2011 Cougar Travel Trailers and Fifth Wheels Production Dates: 6/10/2010 – 9/2/2010
VIN Range: 4YDF26S23**B2502155** - 4YDF32721**B2504257**

2011 Fuzion Travel Trailers and Fifth Wheels Production Dates: 6/10/2010 – 9/2/2010
VIN Range: 4YDF39825**BF810264** - 4YDT29529**BF810679**

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in the vehicles listed above and as a result is conducting a safety recall. We apologize for any inconvenience this action may cause; however the safety and satisfaction of our customers are of the utmost importance to us.

Reason for this recall

It has been decided the Siemens and Murray one inch plug-in circuit breakers, single pole 15 and 20 amp and double pole 50 amp with a June 2010 date code “0610” or July 2010 date code “0710”, may have a non-conforming "spring clip" plug-in assembly that breaks or fails to provide sufficient force to maintain a proper electrical connection in the panel board. Over time, this condition could lead to excessive temperature, arcing or thermal damage at the connection point leading to an increased risk of fire.

What we will do

Keystone has notified our dealers regarding this situation. The remedy is to inspect the single 15 and 20 amp and double 50 amp breakers and replace it if the date code is 0610 or 0710. The service and parts required for this corrective action will be provided at no charge to you.

What we need you to do

At your earliest convenience, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately one hour. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

If you have questions

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. If your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you, please contact Keystone Customer Service by calling 1-866-425-4369.

If after contacting Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>.)