



**RECREATIONAL VEHICLE SAFETY RECALL NOTICE**

Original Notice Date: May 1, 2007

Safety Recall: 07V-164

Canadian Recall: 07-135

Service Advisory: 07-081

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in certain model year 2007 Montana Fifth Wheels. As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

**MODELS AND SERIAL NUMBERS AFFECTED**

**Models Included: 2007 Montanas**

**Serial Number Range: 74703254 – 74703403 (some units were repaired at Keystone prior to shipment)**

***Reason for this recall***

The taillight sockets on your recreational vehicle may not maintain contact with the bulb. As a result the taillights may not function reliably. Failure to remedy this situation may result in an increased risk of a rear end collision while driving due to other drivers not being warned of your stopping and/or turning.

***What we will do***

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. They now stand ready to inspect the taillight sockets and replace them if necessary. The service and parts required for this corrective action will be provided at no charge to you.

***What we need you to do***

At your earliest convenience, please make an appointment to have your Montana serviced by your dealership. The labor time to perform this correction is approximately 1 hour. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your Montana for this repair.

***If you have questions***

Your Montana dealer is best equipped to obtain parts and provide service to ensure your Montana is corrected as promptly as possible. If your dealer is unable to assist or if you take your Montana to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you, please contact Keystone Customer Service by calling 1-866-425-4369.

In the USA, if your dealer fails or is unable to remedy this defect without charge and within a reasonable time period, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>.)

In Canada, you may also submit a written complaint to: Head of Recalls Road Safety and Motor Vehicle Regulation, Transport Canada, 2780 Sheffield Rd., Ottawa, Ontario K1B 3V9. You may also call at 1-613-993-9851.

Thank you for your attention and cooperation in this matter.

Sincerely,

**KEYSTONE RV COMPANY**

Rick Deisler  
Sales & Service Manager

**2642 Hackberry Drive – Goshen, IN 46526**  
**Phone: (574) 535-2100 – Fax: (574) 535-2199**  
**[www.keystonerv.com](http://www.keystonerv.com)**

