



**Keystone RV
Company**

**RECREATIONAL VEHICLE
SAFETY RECALL NOTICE**

Safety Recall: 15V-409
Transport Canada: 2015-287
Safety Advisory: 15-232
July 9, 2015

Recall Population

2014 Mountaineer Model 375FLF Fifth Wheels
Serial Number Range: E4730484 - E4730580

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in the vehicles listed above. As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

***Reason for
this recall***

It has been decided the vehicles identified in this recall population may have been manufactured with a rear window that is intended as the secondary emergency exit and may be blocked by the rear ladder. If an emergency situation arises and the occupants of the vehicle attempt to use the rear window as an emergency exit point they will not be able to exit resulting in an increased risk of personal injury.

***What we
will do***

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. The remedy is to replace the window if the egress is blocked by the ladder. The service and parts required for this corrective action will be provided at no charge to you.

***What we
need you to
do***

As soon as possible, if the window is blocked by the ladder, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately two hours. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair. If the window is not blocked by the ladder, please email ownerrelations@keystonerv.com or call **1-866-425-4369**. You will need to provide the following information:

- VIN
- Name, address and phone number
- A photo showing the window is not blocked by the ladder.

***If you have
questions***

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. If your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you, please contact Keystone Customer Service by calling 1-866-425-4369.

If after contacting Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>.)

