



**Keystone RV  
Company™**

**RECREATIONAL VEHICLE  
SAFETY RECALL NOTICE**

Safety Recall: 18V-383  
Safety Advisory: 18-322  
Transport Canada: 2018-309  
July 30, 2018

**Recall Population**

2018-2019 Keystone Cougar Fifth Wheels and Travel Trailers

Models: 25RES, 26RBS, 26RKS, 27RES, 29BHS, 29RDB, 29RKS, 32BHS, 32DBH, 32RDB, 338RLK, 33MLS, 34TSB, 368MBI, 369BHS, 25BHSWE, 25RESWE, 26RBSWE, 27RESWE, 29BHSWE, 29RDBWE, 30RKSWE, 31BHKWE, 31SQBWE

Serial Number Ranges:

2018 J2503430 - JV513269

2019 K2500235 - KV501824

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in the vehicles listed above. As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

***Reason for  
this recall***

It has been decided that the vehicles in the recall population have an outdoor propane grill installed with clearances that are no longer within the grill manufacturer's specified tolerances to combustible material. Under certain conditions when using the outside propane grill it is possible for the wood assembly the grill is installed in to be exposed to elevated temperatures leading to an increased risk of fire.

***What we  
will do***

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. The remedy is to replace the wood assembly with a metal assembly. The service and parts required for this corrective action will be provided at no charge to you.

***What we  
need you to  
do***

As soon as possible, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately 1 hour. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

***If you have  
questions***

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. Please contact Keystone Customer service if your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you. You may be eligible to receive reimbursement if you paid to have the defect resolved prior to receiving this correspondence. Keystone Customer Service is available toll-free at 1-866-425-4369.

If after contacting Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>.)



**PO Box 2000 – Goshen, IN 46527-2000  
Phone: (574) 535-2100 – Fax: (574) 535-2199  
[www.keystonerv.com](http://www.keystonerv.com)**