



RECREATIONAL VEHICLE SAFETY RECALL NOTICE

Safety Recall USA: 08V-132
Safety Recall Canada: 08-092
Service Advisory: 08-102
2008 Raptor Fifth Wheels Model 3812TS
VIN Range: 4YDF381228R800898 - 4YDF381288R801859

SAFETY RECALL NOTICE

Dear: «Retail_Owner»

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in certain model year 2008 Raptor fifth-wheel recreational vehicles. As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

Reason for this recall

The vehicles subject to this recall campaign have been manufactured with the propane hose for the slide room too close to the tire. The propane line may become damaged as a result of contact with the tire. A propane leak, in the presence of an ignition source, could result in a fire and/or explosion causing property damage and/or personal injury.

What we will do

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. The remedy is to reroute the propane hose away from the tire. If the propane hose is damaged, it will be replaced. The service and parts required for this corrective action will be provided at no charge to you.

What we need you to do

At your earliest convenience, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately one and a half hours. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

If you have questions

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. If your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you, please contact Keystone Customer Service by calling 1-866-425-4369.

If after contacting your dealer and Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>.)

Thank you for your attention and cooperation in this matter.

Sincerely,

KEYSTONE RV COMPANY

Rick Deisler
Sales & Service Manager

cc: National Highway Traffic Safety Administration (NHTSA)



2642 Hackberry Drive – Goshen, IN 46526
Phone: (574) 535-2100 – Fax: (574) 535-2199
www.keystonerv.com