



RECREATIONAL VEHICLE SAFETY RECALL NOTICE

Original Notice Date: April 3, 2006

Safety Recall: 06V-086

Canadian Recall: 06-071

Service Advisory: 06-066

REASON FOR THIS RECALL

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in certain 2006 Keystone RV Mountaineers. The fifth-wheels were built with a 12 volt light in the bunk room mounted on the rear wall. If the light is left on and the bunks are in the up position this light could make contact with mattress, causing the mattress to become scorched or result in a fire.

MODELS AND SERIAL NUMBERS AFFECTED

Models Included: Mountaineer 342PHT Fifth Wheel

Serial Number Range: 4YDF342216F708428 - 4YDF344286F709041

WHAT WE WILL DO

A notice has been sent to your selling dealership regarding this situation. The Dealers stand ready to assist you in addressing this condition by removing the existing light from wall and attaching a new rechargeable flash light in its place. This remedy will be performed at no charge to you.

WHAT YOU SHOULD DO

At your earliest convenience, please make an appointment to have your fifth-wheel serviced by your dealership. The recreational vehicle will need to be at the dealer to perform this service correction approximately one hour. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your travel trailer.

Your Keystone RV dealer is best equipped to obtain parts and provide service to ensure your fifth-wheel is corrected as promptly as possible. If your dealer is unable to assist, please contact Keystone Customer Service by calling 1-866-425-4369. If you take your fifth-wheel to your dealer on the agreed service date, and the Dealer does not remedy the condition within a reasonable amount of time, or without charge to you, please contact Keystone Customer Service by calling 1-866-425-4369.

In the USA, if your dealer fails or is unable to remedy this defect without charge and within a reasonable time period, you may also submit a written complaint to Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>.)

In Canada, you may also submit a written complaint to: Head of Recalls Road Safety and Motor Vehicle Regulation, Transport Canada, 2780 Sheffield Rd., Ottawa, Ontario K1B 3V9. You may also call at 1-613-993-9851.

We regret any inconvenience this action may cause you. As we are sure you will appreciate, the safety of our customers and the quality of our products are of the utmost importance to us.

Thank you for your attention and cooperation in this matter.

Sincerely,

KEYSTONE RV COMPANY

Rick Deisler
Sales & Service Manager

2642 Hackberry Drive – Goshen, IN 46526
Phone: (574) 535-2100 – Fax: (574) 535-2199
www.keystonerv.com